

# *Sentinel* **787**

## **SPECIALTY MASTIC REMOVER**

- 100% Organic
- Noncaustic– Noncorrosive
- Over 140° Flash Point
- Removes acrylic & asphaltic adhesives

### SPECIFICATIONS

APPEARANCE.....	AMBER	ODOR.....	STRONG/SOLVENT
APPROX. BOILING POINT.....	352-418°F	FLASHPOINT.....	147°F
pH.....	NEUTRAL	SPECIFIC GRAVITY (TEMP 60°F).....	900

### DIRECTIONS

#### **For Asphaltic Mastic**

**Step 1.** Pour Sentinel 787 directly on a section of adhesive to be removed. Be sure to apply enough product so that during agitation you are working with a liquid.

**Step 2.** Immediately agitate with a stiff bristled broom or floor brush as this will accelerate the removal process and conserve product, time and effort.

**Step 3.** To conserve product, use a squeegee to push liquefied mastic onto next section and repeat above procedures on all remaining sections.

**Step 4.** Using an absorbent, pick up liquefied material and dispose of according to Federal, State, County and Local regulations.

**Step 5.** Pressure washers used in conjunctions with wet vacs ensure a clean surface. In areas where a pressure washer cannot be used, rinse surface with a mop with water and detergent. Be sure to let the surface dry thoroughly. Once dry, concrete will be ready for flooring.

#### **For Acrylic Mastic**

Simply follow the directions outlined above with these exceptions; Apply 787 and allow it time to saturate and soften mastic so that it can be scraped. After scraping, reapply 787 and agitate with stripping pads.

Caution: Do not allow 787 to enter areas that it cannot be efficiently cleaned from. Residual product will leave a lingering odor.

For additional information, contact Sentinel's Customer Service at 800-373-0633 or on the web at [www.senpro.com](http://www.senpro.com)

51 NE 77th Ave  
Mpls, MN 55432



800-373-0633  
Fax 763-571-1819